



SREDSTVA IN OPREMA ZA KERAMIKO

KAJAKAŠKA 40, 1000 LJUBLJANA, SLOVENIJA
TEL ++386 1 511 00 82
FAX ++386 1 511 00 83
GSM 041/ 68 66 25
e-mail: pika.doo@siol.net
http: www.pika-kilns.com
Ident za DDV : SI 61801780

INSTRUCTION HOW USE ELECTRIC GLORY HOLE

Glory hole use on temperature which is necessary to get good results.
If it is enough 1200 ° C, than 1200 ° C, not 1300 ° C! Every degree
lower than 1300 ° C - **longer life time of every part.**

Regulator has possibility to program time of switch on. GRADIENT of
rising temperature is 400 ° C per hour. That means 3 hours to 1200 ° C.
From 1270 ° C to 1300 arrive on 4 minutes.

Pneumatic pedal has three positions:

close, open and in the middle you can stop door on every position.

Pneumatic needs minimal 6 bars pressure.

MAINTENANCE: Every two months clean drops of glass and paint
with kaolin.

WARRANTY: 24 months except mechanical damages.

Ljubljana, 28. July 2010